

Product Change Notification

107461 - 02

Product Change Notification

1. Updated BIOS to version MQ96510J.86A.1676. Please refer to

notes.
2. Improved board power design to increase compatibility robustness with wider range of power supply units.

Customer Impact of Change and Recommended Action:

The changes have been thoroughly evaluated to ensure there is no quality, reliability or functional impact to customers.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change AA	Post Change TA	Post Change AA
BLKDG965RYCK 878690	878690	D45922-204	D41691-207	D45922-205	D41691-208
BOXDG965RYCK 878695	878695	D45927-205	D41691-207	D45927-206	D41691-208

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
April 10, 2007	00	Originally Published PCN
April 10, 2007	01	Incorrect product code inserted
April 18, 2007	02	Bios revision updated