

Product Change Notification

106974 - 03

Product Change Notification

Update SIO from SCH5017D to SCH5027D. Update BIOS to R37 for quad-core processor support and one resistor change for customer front pannel power LED issue and Adding California perchlorate documentation.

Customer Impact of Change and Recommended Action:

Orders for post-change product need to be placed using the new MM #.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change Product Code	Post Change MM#	Post Change TA	Post Change PBA
BPTHBB 885342	885342	D67881-204	D60097-204	BPTHBB	888000	D67881-205	D60097-205
BPTVBB 885343	885343	D67882-204	D60098-204	BPVBB	888001	D67882-205	D60098-205
S3000PTH 885344	885344	D72613-204	D60097-204	S3000PTH	888003	D72613-205	D60097-205

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
November 8, 2006	00	Originally Published PCN
December 10, 2006	01	Change the BIOS vesion and one resistor change for customer front pannel power LED issue
December 18, 2006	02	Adding California perchlorate documentation
December 20, 2006	03	BIOS version change